

STATEMENT ACCOMPANYING FORM-A.

- | | |
|---|--|
| 1. Name and Door No. of Building | M/s. ARULMIGU MEENAKSHI AMMAN
PUBLIC SCHOOL |
| 2. Location (Street Name, Ward No., Name of Place (Corporation, Municipality, Panchayat, Panchayat Union, Township, Cantonment) | S. No. 376/3B, 3C, 3D & 3E, R. S. No. 376/13,
Alapakkam Main Road, Porur Post,
Maduravoyal Taluk, Chennai – 600116. |
| 3. Year of Construction | 2003. |
| 4. Approximate Cost of Construction | About Rs. 2.40 Crores |
| 5. Purpose for which the building is being used or purpose to be used | School |
| 6. Purpose for which the building hitherto been used | —do— |
| 7. Details of construction of the building (particulars) of the foundation soil, specification of the various parts under | |
| 1. Foundation: | Independent RCC Column footings. |
| 2. Basement: | Brick work in CM over RCC plinth beams. |
| 3. Superstructure: | Four storied Building (GF+FF+SF+TF) RCC framed structure with brick walls in CM plastered over with CM on both sides. It has mostly CC flooring. |
| 4. Floor and Roof (are to be given): | Carpet Area is about 19,500 Sq. Ft. |
| 8. Period for which license is required: | 01-06-2019 to 31-05-2022 (Three Years) |
| 9. Number of persons to be accommodated: | 1500 Persons |

Dated: 20.06.19



D. N. Gupta
Signature of the Engineer.
D. N. GUPTA B.E.M Sc(Engg) Ph.D
FIE FIV FIGS MISET
Chartered Engineer & Regd Valuer
No.6, Damodara Murthy Road,
Kilpauk, Chennai-600 010.
Ph: 2383 7146 (O) & 26443164 (R)
Mobile: 9840831653

R. Gopalthi
Signature of the Owner of the Building
CORRESPONDENT

Arulmigu Meenakshi Amman Public School
Alapakkam, Chennai - 600 116

FORM - B

I certify that the building of M/s. ARULMIGU MEENAKSHI AMMAN PUBLIC SCHOOL, S. No. 376/3B, 3C, 3D & 3E, R. S. No. 376/13, Alapakkam Main Road, Porur Post, Maduravoyal Taluk, Chennai - 600116 was inspected on 27-05-2019 mentioned in the statement below. I have satisfied myself that the building structurally sound to be used as a Public Building for the purposes noted in the statement. The structural soundness of the building has been verified taking into account the loading as per the latest Indian Standards IS: 895. The scope of this Stability Certificate is limited only to the structural soundness of the subject building (and no other structure in the premises) as per BIS 456 - 2000; this does not include the eventualities caused by natural calamities like cyclone, earthquakes, high gales & storm, lightening, floods, fire etc. Certified that no thatched buildings are used in the premises.



Signature of the Engineer.




Dr B N GUPTA BE M Sc(Engg) Ph D
FIE FIV FIGS MISET
Chartered Engineer & Regd Valuer
No.6, Damodara Murthy Road,
Kilpaek, Chennai-600 010.
Ph: 2363 7146 (O) & 26443164 (R)
Mobile: 9840831653

Certified that no addition or alteration has been made to existing building or portion of a building for which this application has been made. I undertake to obtain a fresh license in case any addition or alteration is made to the existing building or portion of building. I also undertake to obtain a license if the purpose for which the license was granted for the use of the building or a portion of the building originally is changed or altered subsequently.

If any thatched buildings are constructed after the issue of this license, we are held responsible for any fire accident that occurs later and that we are aware that our license will be cancelled.

Date:



Signature of the Owner of the Building
CORRESPONDENT
Anulmigu Meenakshi Amman Public School
Alapakkam, Chennai - 600 116

FORM – C

(Form of certificate of structural soundness under sub-section (4) of Section 4 of the Tamil Nadu Public Building (Licensing) Act 1965 (Tamil Nadu Act 1 of 1965) referred to in Rule 4 of the Tamil Nadu Public Buildings (Licensing) Rules, 1966.

εεεεεεεεεε

I certify that the building mentioned in the statement and furnished below the salient technical features was inspected.

1. Foundation:

- i. Depth below ground level: 2.43 M
- ii. Nature of soil set out in the foundation level: Sandy Clay.
- iii. Pressure at foundation: About 12.00 t/Sq.m.
- iv. Probable safe bearing capacity of strata met at the foundation: About 15.00 t/Sq.m.

2. Superstructure:

- i. Maximum stress in the most critical section of masonry and concrete
- | | |
|---------------------|------------------|
| a. Brick Work in CM | = 0.50 kg/Sq.cm |
| b. RCC | = 30.00 kg/Sq.cm |
- ii. Nature of masonry and concrete and its safe permissible stress
- | | |
|---------------------|------------------|
| a. Brick Work in CM | = 5.00 kg/Sq.cm |
| b. RCC | = 50.00 kg/Sq.cm |

The structural soundness of the building has been verified by me with reference to ISI loading standards IS: 895 (latest version) and other relevant Indian Standard code of practice and I declare that the building is structurally sound to be used as a public building for the purpose noted in the statement. A license may be granted for the period from 01-06-2019 to 31-05-2022 (Three Years).

Date: 18.06.19

Place: Chennai-10



Signature of the Engineer



Dr B N GUPTA BE M Sc(Engg) Ph D
FIE FIV FIGS MISET
Chartered Engineer & Regd Valuer
No.6, Damodara Murthy Road,
Kilpauk, Chennai-600 010.
Ph: 2363 7146 (O) & 26443164 (R)
Mobile: 9840631653

STATEMENT TO ACCOMPANY THE CERTIFICATE OF STRUCTURAL SOUNDNESS

Location of the building, Door No., Street Name, and Name of the Place (1)	Age of the Building (2)	Value of Building at Current Rates (3)	No. of Stories (4)	Short description of structure Steel, RCC framed or Load Bearing in Masonry (5)
M/s. ARULMIGU MEENAKSHI AMMAN PUBLIC SCHOOL S. No. 376/3B, 3C, 3D & 3E, R. S. No. 376/13, Alapakkam Main Road, Porur Post, Maduravoyal Taluk, Chennai - 600116	About 16 Years.	About Rs 2.40 crores	Four	Four storied Building (GF+FF+SF+TF) RCC framed structure with brick walls in CM plastered over with CM on both sides. It has mostly CC flooring.

Purpose for which the building is Certified for use. (6)	Period for which the building will be structurally sound (7)	No. of Persons to be accommodated (8)	Remarks (9)
School	01-06-2019 to 31-05-2022 (Three Years)	1500 persons	Building is structurally sound

B. N. Gupta 18.06.19

**Signature of the Engineer
Designation.**



Dr B N GUPTA BE M Sc(Engg) Ph D
FIE FIV FIGS MISET
Chartered Engineer & Regd Valuer
No.6, Damodara Murthy Road,
Kilpauk, Chennai-600 010.
Ph: 2363 7146 (O) & 26443184 (R)
Mobile: 9840831653

FORM - E

(Form of Report to be made to the competent authority by inspecting authorities or officers appointed under other act under Section 25 of Madras Public Buildings Authorities Act 1965 (Madras act 13 of 1965) Referred to in rule 7 of the Madras Public Buildings Licensing Rule, 1966.

ε ε ε ε ε ε ε ε

- | | |
|---|---|
| 1. Name and Designation of inspecting authority or officer appointed or having jurisdiction under any other act or law. | : B N Gupta, Panel Engineer (Class IA) of Collector of Chennai for issuing Certificate of Structural Soundness of the public buildings. |
| 2. Location of the building inspected D. No., Street name of place, ie., Municipal Corp. / Municipality / Panchayat / Panchayat Union / Township / Cantonment | : M/s. ARULMIGU MEEENAKSHI AMMAN PUBLIC SCHOOL
S. No. 376/3B, 3C, 3D & 3E, R. S. No. 376/13, Alapakkam Main Road, Porur Post, Maduravoyal Taluk, Chennai - 600116. |
| 3. Date of Inspection | : 27-05-2019. |
| 4. Purpose for which the building is used | : School |
| 5. Nature of defects noticed | : -- Nil -- |
| 6. Suggestion for rectifying defects | : -- Nil -- |
| 7. If in a dangerous conditions immediate action recommended to be taken. | : -- Nil -- |

Date: 18.06.19

Place: Chennai-10



Signature of Inspecting Authority /
Officers appointed or jurisdiction.



Dr B N GUPTA BE M Sc(Engg) Ph D
FIE FIV FIGS MISEY
Chartered Engineer & Regd Valuer
No.6, Damodara Murthy Road,
Kilpauk, Chennai-600 010.
Ph: 2363 7146 (O) & 26443164 (R)
Mobile: 9840631653

Arulmigu Meenakshi Amman Public School,
No.62, Alapakkam Main Road, porur, ch-116.



K. Dia. 3024/2019/A1 dated 01.10.2019
Licence No.152/19 Licence Renewed for 3 years
from 01.06.2019 to 31.05.22 for 1500 persons
Licence fee Rs. 1000/-remitted in Challan No. 47
dated 12.09.19 at S.B.I, Ambattur

Penalty Rs.1000 /has been levied for non-renewal
from 01.06.19 to 05.08.19
Penalty of Rs.1000/-remitted in Challan No.14
dated 02.10.19 at S.B.I, Ambattur

Revenue Divisional Officer,
Central Chennai Division

Handwritten signature and date: 1/10/19